

## DAFTAR PUSTAKA

- Akuan, Abrianto. *Kelelahan Logam*. Bandung: Universitas Jenderal Achmad Yani, 2007.
- Akhamad Ardian Korda. *Mekanika Retakan Analisa Kegagalan*. Youtube Video, 7:30. 31 Agustus 2020. <https://www.youtube.com/watch?v=4XXzZdDyBeQ>.
- Anselmo, Clay. "Failure Investigation and Root Cause Analysis", Reglara Presentation." Reglara Presentation. Diakses pada Selasa 10 Januari 2023. <https://silo.tips/download/failure-investigation-and-root-cause-analysis>.
- Calister, William dan David Rethwisch. *Material Science and Engineering*. Salt Lake: Wiley, 2007.
- Cargill. "Sejarah PT Hindoli" [cargill.com](http://cargill.com). Diakses pada Rabu 5 Januari 2022. <http://cargill.co.id>.
- Danuputro, Sebastianus Dwi. "Investigasi Penyebab Kerusakan Chain Bucket Elevator Pada 7<sup>th</sup> Finish Mill Transport System Area di Tuban IV PT. Semen Gresik." Skripsi. Institut Teknologi Sepuluh November Surabaya, 2016.
- Das, Nilakash, "Models To Explain out-of plane Bending Mechanism in Mooring Chain Links." Tesis, Delft University Of Technology, 2016.
- Jagtap M.D, dkk. "Study of Roller Conveyor Chain Strip Under Tensile Loading." *Internasional Journal Of Modern Engineering Research* 04, no. 5 (2014): 65.
- Joseph R. Davis. *Metals Handbook*. ASM Internasional. ". Texas: ASM Internasional, 1998.
- Kandzia, Ryszard dan Mariusz Szot " Fatigue Life Testing Of The Round Link Mining Chains." *Mangement System in Production Engineering* 31, no. 1 (2013): 79.
- Malinda Miladia. "Investigasi Kegagalan U-Bolt Chain Bucket Elevator M4135 PT. Petrokimia Gresik." Skripsi. Institut Teknologi Sepuluh November, 2016.
- Matanari. 2019. "Analisa Kekuatan Rantai Pada Mini Crane Portable Kapasitas 1 Ton." Skripsi. Universitas Muhammadiyah Sumatera Utara, 2016.
- Ossic. "Inspection Round Link Chain Use." [ChiogongIndustrial.com](http://ChiogongIndustrial.com). Diakses pada tanggal 25 Juli 2023. [scic-chain.com/news/round-link-chain-use-inspection](http://scic-chain.com/news/round-link-chain-use-inspection).

- PT Hindoli. 2022. Data Sheet Downtime Undertow System PT. Hindoli Mill Sungai Lilin, Musi Banyuasin, Sumatera Selatan. Diakses pada tanggal 5 Maret 2023 pukul 09:00 WIB.
- PT Hindoli. 2022. Dokumen Perusahaan PT Hindoli Mill Sungai Lilin, Musi Banyuasin, Sumatera Selatan. Diakses pada tanggal 5 September 2022 pukul 08:00 WIB.
- Sugiarto, Mochamad Ruli. "Investigasi Kerusakan Rantai Bucket Elevator 2205 Di Pabrik Phosphoric Acid (PA) PT. Petrokimia Gresik." Skripsi. Institute Teknologi Sepuluh November, 2016.
- The Engineering Toolbox "Coefficient of Rolling Friction" [engineeringtoolbox.com](https://www.school-forchampions.com/friction_rolling_coefficient.htm). Diakses pada minggu 22 Juli 2023. [https://www.school-forchampions.com/friction\\_rolling\\_coefficient.htm](https://www.school-forchampions.com/friction_rolling_coefficient.htm).
- Tushar D. Bhoite, dkk. "Fea Based Study of Effect of Radial Variation of Outer Link in A Typical Roller Chain Link Assembly". *International Journal of Mechanical and Industrial Engineering*, no. 4 (2012): 1201.
- United States Department Of Labor. 2017. "Occupational Safety and Health Administration." [Osha.com. https://www.osha.gov/laws-regs/standardnumber/](https://www.osha.gov/laws-regs/standardnumber/). Diakses pada tanggal 25 Juli 2023.