

## JOURNAL OBSERVATION

Day / Date : Jumat / 8 Juni 2018

Venue : Islamic Center Prabumulih




1. The outstanding view of the building which attracts the people who enter this building.



2. The access and condition of the road are good. Not only that, the road is also free from litter.



3. In addition to clean and orderly road conditions, the courtyard around this building is surrounded by ornamental plants that make this building look beautiful.



4. Unfortunately, this building has not received maximum attention for maintenance in every corner. This is because the building is rarely used and makes the janitor rarely monitor into the room. They only keep the outside cleanliness around the building.



5. The condition of the bathroom is not good anymore; it looks from the bathroom's door that cannot work well again



6. There was damage in one of the glass that becomes the wall for the building itself.



7. There are some stains attached to the walls of the building.

**Approved by:**

Head of Manager Islamic Center Prabumulih

H. Ali Aman, S. Ag, MM.